

LEDERLE LABORATORIES

SEPA-REGION II
OFFICE OF EMERGENCY &
REMEDIAL RESPONSE

Lederle

A Division of AMERICAN CYANAMID COMPANY

PEARL RIVER, NEW YORK 10965

AREA CODE 914 735-5000

DIRECTOR'S OFFICE

June 28, 1984

Regional Administrator
EPA Region II
26 Federal Plaza
New York, New York 10007

SUB: Contingency Plan Incident Report
REF: Resource Conservation and Recovery Act
Regulations 40 CFR Part 265.56(j).

Attached is a report on an incident which required the implementation of our contingency plan. The report format used follows the information required as listed numerically in the Federal Register.

This submission or any past or future discussion or communication with respect to this matter is not intended to admit liability or to waive any rights.

If you have any questions or require additional information, please contact Mr. T. J. Reilly at this location.

Very truly yours,

A. L. Smith

A. L. Smith
Plant Manager

RECEIVED

JUL 12 1984

Emergency Response
and Inspection Branch
Edison, N. J.

TJR:tp

cc: Mr. Cesare Manfredi
Program Director
NYSDEC
Division of Water
Region III Sub-Office
202 Mamaroneck Avenue, 3rd Floor
White Plains, NY 10601-5381

217046



CORRESPONDENCE CONTROL
REGION II

JUL 9 2 43 PM '84

ENVIRONMENTAL PROTECTION
AGENCY
NEW YORK, N.Y.

CONTINGENCY PLAN INCIDENT REPORT

REFERENCE: Resource Conservation and Recovery Act Regulations,
40 CFR Part 265.56(j)

1. OPERATOR INFORMATION: American Cyanamid Company, Inc.
One Cyanamid Plaza
Wayne, New Jersey 07470
(201) 831-2000
2. FACILITY INFORMATION Lederle Laboratories
Division of American Cyanamid
North Middletown Road
Pearl River, New York 10965
3. DATE, TIME, AND TYPE OF INCIDENT: June 27, 1984, 8:45 A.M.
Tank overflow through tank vent
onto exterior wall of
Manufacturing Building and
pavement two floors below.
4. NAME AND QUANTITY OF MATERIAL: 28% methanol solution (F003).
Approximately two to three
gallons.
5. EXTENT OF INJURIES, IF ANY: None.
6. HAZARDS: None.
7. RECOVERY: Not possible; solvent evaporated
too quickly on the surface of the
building and pavement.